

## Questions for MCC Parking Lot Sealcoat & Restripe

1. Sheets C-04, C1.10, C-03, C1.00, and C-03 of the drawings appear to show a lot more concrete, asphalt, and storm water management work than the Schedule of Prices form has on it. Please clarify if those sheets are supposed to be part of this project.
  - a. Those sheets were included for reference only to provide the contractor an idea of how to restripe the parking lots once sealcoated.
2. If this work is part of the project, please provide details for asphalt, concrete, and storm water management.
  - a. Not part of project; only provided as a reference so the contractor knows how to restripe the parking lots.
3. What depth are the Full Depth Asphalt Patches on sheet EX-1. Please provide a pavement section if available.
  - a. Full depth asphalt patch needs to match existing asphalt section. For reference the proposed pavement section for this parking lot when it was built was 1 ½" surface over 1 ½" binder over 10" CA-6. So minimum asphalt depth would be 3"; however, it could be more depending on how the lot was actually constructed and if there have been any overlays/patching through the years.